

Water Pump Interchange List - OE Numbers

| Their No. | Our No. | Their No. | Our No. | Their No. | Our No. | Their No. | Our No. |
|-----------------------|----------|-------------|----------|----------------------|----------|------------------|----------|
| Acura | | J8125131 | 110-1040 | 078121006X | 180-2120 | 9N1249 | 196-2020 |
| 19200P0A003 | 135-1280 | J8126772 | 110-1010 | 135121004A | 180-1100 | 9N6147 | 196-2041 |
| 19200P1R003 | 135-2430 | J8130749 | 110-1030 | 22121011X | 180-9020 | | |
| 19200P30003 | 135-2200 | J8132274 | 130-1120 | 22121011X | 180-9020 | Checker | |
| 19200P5A004 | 135-2360 | J8133033 | 110-1030 | 68121005B | 180-1010 | 08207 | 130-1010 |
| 19200P5G004 | 135-2220 | J8133034 | 110-1050 | 68121005C | 180-1010 | 09111 | 130-1350 |
| 19200P72003 | 135-2210 | J8134320 | 110-1030 | | | 474028 | 130-1270 |
| 19200P72013 | 135-2390 | J8134321 | 110-1050 | Austin | | 10048917 | 130-1250 |
| 19200P75003 | 135-1270 | MD179030 | 148-1470 | GWP102 | 113-1010 | | |
| 19200P75003 | 135-1400 | MD300799 | 148-1470 | GWP107 | 113-2130 | Chevrolet | |
| 19200P8A02 | 135-2380 | MD972050 | 148-1480 | GWP123 | 113-1050 | 12456328 | 130-9600 |
| 19200P8A03 | 135-2380 | MD972052 | 148-1440 | | | | |
| 19200P8AA02 | 135-2380 | MD997076 | 148-1170 | Austin Healey | | Chrysler | |
| 19200P8AA03 | 135-2380 | MD997418 | 146-1080 | GWP102 | 113-1010 | 342008 | 120-1070 |
| 19200PG6000 | 135-1240 | MD997609 | 148-1170 | GWP107 | 113-2030 | 1054750 | 120-2713 |
| 19200PG6415 | 135-1240 | MD997619 | 148-1190 | GWP108 | 113-2020 | 1064750 | 120-2713 |
| 19200PH7003 | 135-1250 | MD997621 | 148-1440 | | | 1325973 | 120-2713 |
| 19200PR4003 | 135-1270 | MD997622 | 148-1450 | BMW | | 1603326 | 120-2713 |
| 19200PR4013 | 135-1270 | T1463182 | 157-2050 | 11511714212 | 115-2230 | 1752422 | 120-1250 |
| 19200PR7A02 | 135-2085 | T1464552 | 120-3066 | 11511714212 | 115-2230 | 1818610 | 120-1200 |
| 19200PR7A03 | 135-2085 | | | 11511741980 | 115-2200 | 1879526 | 120-1200 |
| 19200PRBA01 | 135-6930 | Audi | | 11511741980 | 115-2200 | 1879536 | 120-1200 |
| 19200PRBA01 | 135-6930 | 026121005E | 180-1070 | 11517527910 | 115-3090 | 2196035 | 120-1060 |
| 19200PRBA01 | 135-1510 | 026121005H | 180-1070 | 11511251230 | 115-1050 | 2196910 | 120-1060 |
| 19200PV1A01 | 135-2090 | 026121005K | 180-2230 | 11511251236 | 115-1050 | 2421375 | 120-1250 |
| 19200PV3003 | 135-2090 | 034121004 | 180-2050 | 11511256316 | 115-2020 | 2448315 | 120-1250 |
| 19200PY3010 | 135-1350 | 034121004A | 180-2050 | 11511256600 | 115-1070 | 2448326 | 120-1200 |
| 19200PY3A00 | 135-1360 | 035121004A | 180-1100 | 11511258933 | 115-1010 | 2448328 | 120-1200 |
| 19200RBB003 | 135-1500 | 035121005C | 180-2130 | 11511312574 | 115-2060 | 2525098 | 120-2907 |
| 19200RCAA01 | 135-6940 | 035121005E | 180-1100 | 11511315292 | 115-2085 | 2585291 | 120-1220 |
| 19200RCAA01 | 135-6940 | 050121010 | 180-2230 | 11511406650 | 115-2190 | 2585384 | 120-1200 |
| 19200RDMA01 | 135-6940 | 050121010A | 180-2230 | 11511407806 | 115-2180 | 2585385 | 120-2907 |
| 19200RDMA01 | 135-6940 | 054121004A | 180-2070 | 11511433828 | 115-2090 | 2808464 | 120-1200 |
| 8971259750 | 140-1340 | 059121011F | 180-1080 | 11511705236 | 115-1050 | 2808466 | 120-1200 |
| 8971675540 | 140-1440 | 068121005A | 180-1070 | 11511706588 | 115-1040 | 2808649 | 120-1210 |
| | | 068121005B | 180-1010 | 11511707414 | 115-1050 | 2808679 | 120-1060 |
| Alfa Romeo | | 069121005D | 180-1060 | 11511713266 | 115-2130 | 2808680 | 120-1200 |
| 60519187 | 112-2010 | 06A121011F | 180-2220 | 11511713266 | 115-2130 | 2808681 | 120-1200 |
| 60534758 | 112-2070 | 06A121011L | 180-2220 | 11511714212 | 115-2150 | 3004715 | 120-1220 |
| 60555345 | 112-2020 | 06A121011LX | 180-2220 | 11511719836 | 115-1080 | 3004762 | 120-1250 |
| 60555348 | 112-2050 | 06C121004C | 180-9010 | 11511720883 | 115-1060 | 3004763 | 120-2907 |
| 60559314 | 112-2040 | 06C121004C | 180-9010 | 11511720892 | 115-1060 | 3004866 | 120-1210 |
| 60711594 | 112-2030 | 06C121004G | 180-9010 | 11511720893 | 115-1060 | 3004886 | 120-7132 |
| 60712573 | 112-2060 | 06C121004G | 180-9010 | 11511721477 | 115-1020 | 3004991 | 120-1250 |
| | | 06C121004H | 180-9010 | 11511721872 | 115-2080 | 3420037 | 120-1070 |
| Allis Chalmers | | 06C121004H | 180-9010 | 11511722536 | 115-2090 | 3420038 | 120-1070 |
| 250396 | 196-2016 | 06C121004HX | 180-2120 | 11511729359 | 115-2095 | 3420050 | 120-1060 |
| 250397 | 196-2013 | 06C121004HX | 180-2120 | 11511729741 | 115-2070 | 3420225 | 120-2940 |
| 5135595 | 130-3074 | 06C121004HX | 180-9010 | 11511731680 | 115-2100 | 3683834 | 120-1200 |
| 5135596 | 130-3058 | 06C121004HX | 180-9010 | 11511734595 | 115-2080 | 3745985 | 120-7132 |
| 5135596 | 130-3078 | 077121004A | 180-2080 | 11511734596 | 115-2080 | 3780108 | 120-1070 |
| | | 077121004F | 180-2260 | 11511734602 | 115-2080 | 3780109 | 120-1070 |
| AMC/Eagle | | 077121004H | 180-2260 | 11511734872 | 115-2080 | 3780127 | 120-1200 |
| 4556541 | 120-1310 | 077121004M | 180-2260 | 11511741980 | 115-2140 | 3780196 | 120-4170 |
| 4663296 | 120-1320 | 077121004M | 180-2260 | 11511742517 | 115-2110 | 3837641 | 120-1070 |
| 4667660 | 120-1300 | 077121004M | 180-2250 | 11511742647 | 115-2120 | 3879716 | 120-1098 |
| 5281175 | 120-1290 | 077121004MV | 180-2250 | 11511744243 | 115-2090 | 4106034 | 120-1060 |
| 83502957 | 110-1070 | 077121004MV | 180-2250 | 11512241641 | 115-2190 | 4131243 | 120-1060 |
| 83503407 | 110-1080 | 077121004MX | 180-2250 | 1151720892 | 115-1060 | 4173703 | 120-1190 |
| 89502938 | 110-1060 | 077121004MX | 180-2250 | 11517503884 | 115-2090 | 4293898 | 120-1050 |
| 4663296AB | 120-1340 | 077121004MX | 180-2250 | 11517504040 | 115-2090 | 4323148 | 120-1050 |
| J1466241 | 120-3065 | 078121004C | 180-2090 | 11517527910 | 115-2090 | 4387457 | 120-1260 |
| J3205620 | 110-3021 | 078121004H | 180-2120 | | | 4429404 | 120-3072 |
| J3207294 | 110-2843 | 078121004J | 180-2120 | Case | | 4448878 | 120-1270 |
| J3207676 | 110-2843 | 078121004L | 180-2120 | A146584 | 196-2024 | 4483453 | 120-1280 |
| J3227694 | 110-1040 | 078121006 | 180-2120 | G11956 | 196-2014 | 4483754 | 120-3020 |
| J3234427 | 110-1040 | 078121006A | 180-2240 | | | 4556541 | 120-1310 |
| J8120129 | 110-2843 | 078121006A | 180-2240 | Caterpillar | | 4621172 | 120-1280 |
| J8120130 | 110-2908 | 078121006A | 180-2240 | 2W1225 | 196-2041 | 4621489 | 120-1330 |
| J8120236 | 110-2986 | 078121006X | 180-2120 | 2W1227 | 196-2043 | 4626682 | 120-3060 |
| J8120286 | 110-2986 | 078121006X | 180-2120 | 7W7019 | 196-2035 | 4663296 | 120-1320 |

Water Pump Interchange List - OE Numbers

| Their No. | Our No. | Their No. | Our No. | Their No. | Our No. | Their No. | Our No. |
|-------------------------|----------|---------------------------|----------|-----------------------|----------|-----------|----------|
| Chrysler (Cont.) | | MD977705 | 148-1510 | AR513600 | 196-2033 | B6C8501C | 125-2756 |
| 4663732 | 120-4190 | MD978743 | 148-2320 | AR61788 | 196-2048 | B6C8501D | 125-2756 |
| 4667660 | 120-1300 | MD980000 | 148-1400 | | | CODE8507A | 125-1290 |
| 4694307 | 120-4220 | MD997076 | 148-1170 | Daewoo | | CODE8587A | 125-1290 |
| 4763776 | 120-4160 | MD997078 | 148-1190 | 90466343 | 121-2002 | CODZ8501A | 125-1290 |
| 4792195 | 120-1350 | MD997079 | 148-1230 | 92064250 | 121-2002 | CODZ8501B | 125-1290 |
| 4992195 | 120-1350 | MD997081 | 148-1270 | 96352652 | 121-2001 | CODZ8501C | 125-1290 |
| 5203432 | 120-1050 | MD997082 | 148-1130 | | | C2OZ8501A | 125-2819 |
| 5214490 | 120-1040 | MD997149 | 148-1130 | Daihatsu | | C2OZ8501B | 125-2819 |
| 5245357 | 120-3080 | MD997158 | 148-1370 | 1610019075 | 122-2020 | C2OZ8501C | 125-2819 |
| 5245465 | 120-3090 | MD997178 | 148-1370 | 1610019076 | 122-2020 | C2OZ8501C | 125-2819 |
| 5245720 | 120-3090 | MD997244 | 148-1400 | 161008718300 | 122-2030 | C3OZ8501B | 125-2819 |
| 5281175 | 120-1290 | MD997404 | 148-2130 | 161008718300 | 122-2030 | C4TZ8501G | 125-2881 |
| 12371989 | 130-1480 | MD997418 | 146-1080 | 1610087184000 | 122-1320 | C4TZ8501H | 125-1430 |
| 53008354 | 120-3071 | MD997418 | 148-1530 | 1610087185 | 122-1320 | C5AZ8501B | 125-2819 |
| 53020280 | 120-3041 | MD997421 | 148-1190 | 1610087185 | 122-1350 | C5AZ8501C | 125-1370 |
| 53021018 | 120-3041 | MD997515 | 148-1400 | 1610087797000 | 122-1340 | C5AZ8501C | 125-2819 |
| 71244450 | 120-1170 | MD997609 | 148-1170 | | | C5AZ8501D | 125-1370 |
| 4626054AD | 110-1090 | MD997614 | 148-1270 | Desoto | | C5AZ8501E | 125-1420 |
| 4626054AE | 110-1090 | MD997615 | 148-1230 | 1064750 | 120-2713 | C5AZ8501F | 125-1370 |
| 4663296AB | 120-1340 | MD997619 | 148-1190 | 1818610 | 120-1200 | C5AZ8501F | 125-1420 |
| 4663732AB | 120-4190 | MD997622 | 148-1450 | 2808680 | 120-1200 | C5AZ8501G | 125-1370 |
| 4663732AC | 120-4190 | MD997634 | 148-1400 | 3683834 | 120-1200 | C5AZ8501G | 125-1370 |
| 4663732AC/AD | 120-4190 | MD997643 | 148-1500 | | | C5AZ8501H | 125-1420 |
| 4663732AC/AD | 120-4190 | MDO21490 | 148-1130 | Detroit Diesel | | C5AZ8501H | 125-1420 |
| 4667660AB | 120-1300 | | | 5135596 | 130-3058 | C5AZ8501J | 125-1410 |
| 4667660AE | 120-1300 | Clark | | 5135596 | 130-3074 | C5AZ8501K | 125-2819 |
| 4694307AB | 120-4220 | 865707 | 196-0655 | 5149328 | 196-2031 | C5AZ8501L | 125-1420 |
| 4694307AC | 120-4220 | 865774 | 196-0651 | 5149329 | 196-2038 | C5AZ8501M | 125-1370 |
| 4694307AE | 120-4220 | 909301 | 148-2500 | 5149708 | 196-2026 | C5AZ8501M | 125-1370 |
| 4763776AB | 120-4160 | 915729 | 148-2501 | 5149710 | 196-2027 | C5AZ8501N | 125-1370 |
| 4781157AA | 120-4230 | 1603326 | 120-2713 | 8922335 | 196-2037 | C5AZ8501P | 125-1420 |
| 4792195AB | 120-1350 | 3768063 | 148-1120 | 8922336 | 196-2036 | C5AZ8501R | 125-1370 |
| 4792195AB | 120-1350 | 3768064 | 148-1260 | 8928672 | 196-2034 | C5AZ8501S | 125-1370 |
| 4792838AA | 120-7150 | F162K3653 | 196-0651 | | | C5AZ8501T | 125-1420 |
| 4792838AA | 120-7150 | Y400K3612 | 196-0655 | Divco Truck | | C5AZ8501U | 125-1370 |
| 4884159AA | 120-4360 | | | BGC8501C | 125-2756 | C5NN8501A | 125-2872 |
| 5010898AA | 120-1270 | Co Op Tractor | | BGC8501D | 125-2756 | C5NN8501E | 125-1200 |
| 5010964AA | 120-3072 | 1603326 | 120-2713 | | | C5OZ8501A | 125-2819 |
| 5010964AB | 120-3072 | | | Dodge | | C5OZ8501E | 125-1420 |
| 5086959AA | 120-3072 | Continental Motors | | ME007264 | 120-7160 | C5OZ8501F | 125-1420 |
| 53020873AB | 120-4350 | 830691M91 | 196-2007 | | | C5OZ8501G | 125-1420 |
| 53020873AC | 120-4350 | 8560514M91 | 196-2007 | Eaton | | C5TZ8501B | 125-1680 |
| 53021018AB | 120-3041 | F162K3653 | 196-0651 | D3JL8501C | 125-5009 | C5TZ8501C | 125-1680 |
| 53021018AC | 120-3041 | Y400K3612 | 196-0655 | | | C6AE8501M | 125-1370 |
| 53021018AD | 120-3041 | Z120K3051 | 196-2009 | Fiat | | C6AZ8501A | 125-1410 |
| 53021187AA | 120-4350 | | | 4129810 | 123-1040 | C6AZ8501B | 125-1410 |
| 53021187AA/G/K/L | 120-4370 | Cummins Diesel | | 4269431 | 123-1090 | C6AZ8501C | 125-1410 |
| 53021187AA/G/K/L | 120-4370 | 377411 | 196-2054 | 4331825 | 123-1030 | C6DZ8501A | 125-1290 |
| 53021380AK | 120-4370 | 3004923 | 196-2044 | 4384128 | 123-1010 | C6DZ8501B | 125-1290 |
| J1464552 | 120-3066 | 3022471 | 196-2029 | 4429224 | 123-1120 | C6DZ8501C | 125-1290 |
| J1466241 | 120-3065 | 3027174 | 196-2060 | 4429226 | 123-2020 | C6DZ8501D | 125-1290 |
| MD001300 | 148-1010 | 3027882 | 196-2028 | 43297761 | 123-2030 | C8AZ8501A | 125-1370 |
| MD008431 | 148-1150 | 3045943 | 196-2032 | 43297761 | 123-2060 | C8AZ8501A | 125-1370 |
| MD009000 | 148-1120 | 3062931 | 196-2065 | | | C8AZ8501B | 125-1370 |
| MD021450 | 148-1030 | 3065000 | 196-2064 | Ford | | C8AZ8501L | 125-1370 |
| MD021490 | 148-1130 | 3066330 | 196-2045 | 105E8501A | 125-1020 | C8SZ8501A | 125-2893 |
| MD025190 | 148-1220 | 3802081 | 196-2047 | 1F1Z8501AA | 125-1820 | C8SZ8501A | 125-2893 |
| MD030751 | 148-1140 | 3802358 | 120-3072 | 1L2Z8501BA | 125-5990 | C8SZ8501B | 125-2893 |
| MD030863 | 148-1170 | 3803138 | 196-2062 | 1L2Z8501BA | 125-5990 | C8SZ8501B | 125-2893 |
| MD034152 | 148-1190 | 3803402 | 196-2063 | 1L2Z8501BB | 125-5990 | C8SZ8501C | 125-2893 |
| MD179030 | 148-1470 | 14079005 | 196-2054 | 1L2Z8501BB | 125-5990 | C8SZ8501C | 125-2893 |
| MD300799 | 148-1470 | 14079055 | 196-2054 | 1L2Z8501BB | 125-5990 | C8VZ8501A | 125-2893 |
| MD971538 | 148-1480 | 34079B05 | 196-2054 | 1L3Z8501AB | 125-6010 | C9AV8501A | 125-2893 |
| MD972001 | 148-1390 | A34079A05 | 196-2048 | 1S7Z8501AK | 125-6000 | C9AZ8501A | 125-1420 |
| MD972003 | 148-1400 | AR4283 | 196-2002 | 1W9Z8501AA | 125-6030 | C9DZ8501A | 125-1380 |
| MD972005 | 148-1500 | AR4284 | 196-2042 | 2R8Z8501AE | 120-6040 | C9TZ8501A | 125-1230 |
| MD972050 | 148-1480 | AR45073 | 196-2029 | 2S7Z8501BG | 125-6060 | C9VZ8501A | 125-2893 |
| MD972052 | 148-1440 | AR45090 | 196-2000 | 3F2Z8501BB | 125-1970 | C9Z8501A | 125-1420 |
| MD973025 | 148-1510 | AR45184 | 196-2001 | 3L3Z8501CA | 125-6050 | CODE8507A | 125-1290 |
| MD973940 | 148-1400 | AR45189 | 196-2045 | 4S4Z8501AA | 125-6000 | CODZ8501C | 125-1290 |
| | | | | | | D0AZ8501A | 125-1110 |

Water Pump Interchange List - OE Numbers

| Their No. | Our No. | Their No. | Our No. | Their No. | Our No. | Their No. | Our No. |
|--------------|----------|-------------|----------|-------------|----------|-----------------------|----------|
| Ford (Cont.) | | D77Z8501A | 145-1100 | E9TZ8501B | 125-5018 | F6TZ8501KB | 125-1810 |
| D0AZ8501A | 125-1370 | D7HZ8501C | 125-4096 | EOAZ8501A | 125-1700 | F6ZZ8501A | 125-1940 |
| D0AZ8501C | 125-1110 | D7HZ8501D | 125-1450 | F0Z8501B | 125-5059 | F7Z8501AD | 125-2102 |
| D0AZ8501D | 125-1370 | D7HZ8501E | 125-4096 | F0AZ8501A | 125-1700 | F7BZ8501A | 145-1310 |
| D0AZ8501E | 125-1110 | D7HZ8501F | 125-1450 | F0CZ8501A | 125-1690 | F7CA8501AB | 125-1990 |
| D0AZ8501F | 125-1230 | D7HZ8501F | 125-4093 | F0DZ8501A | 125-5532 | F7CZ8501AB | 125-1990 |
| D0OZ8501A | 125-1230 | D8BZ8501A | 125-1280 | F0PZ8501A | 125-1340 | F7DZ8501A | 125-1950 |
| D0OZ8501A | 125-1380 | D8FZ8501A | 145-1200 | F0TE8501E | 125-1670 | F7TZ8501AB | 125-1770 |
| D0OZ8501B | 125-1230 | D8HZ8501A | 125-4093 | F0TZ8501D | 125-1770 | F7TZ8501AD | 125-2101 |
| D0OZ8501C | 125-1230 | D8HZ8501B | 125-4010 | F0TZ8501E | 125-1670 | F7TZ8501CRM | 125-5930 |
| D0OZ8501C | 125-1350 | D8RZ8501A | 125-1100 | F0TZ8501F | 125-1620 | F7UC8501CA | 125-1980 |
| D0RY8501A | 125-1010 | D8TZ8501B | 125-1350 | F0TZ8501G | 125-1770 | F7UZ8501CA | 125-5890 |
| D0TZ8501B | 125-1430 | D8ZZ8501A | 125-1240 | F0ZZ8501A | 125-1560 | F7UZ8501DA | 125-5920 |
| D0VZ8501A | 125-1350 | D9AZ8501A | 125-1700 | F1CZ8501A | 125-1720 | F81Z8501AA | 125-5920 |
| D0ZZ8501A | 125-1230 | D9HZ8501A | 125-5037 | F1HZ8501C | 125-4071 | F81Z8501ARM | 125-5930 |
| D1AZ8501A | 125-1110 | D9ZZ8501A | 125-1560 | F1HZ8501CRM | 125-4071 | F81Z8501CRM | 125-5930 |
| D1DZ8501A | 125-1380 | D9ZZ8501A | 125-1570 | F1HZ8501D | 125-5072 | F81Z8501DA | 125-5920 |
| D1FZ8501A | 125-1030 | E0AZ8501A | 125-1700 | F1HZ8501DRM | 125-5072 | F85Z8501AA | 125-2101 |
| D1FZ8501B | 125-1010 | E1AZ8501A | 125-1440 | F1HZ8501E | 125-5037 | F87Z8501A | 125-1960 |
| D1FZ8501B | 125-1030 | E1AZ8501A | 125-1440 | F1SZ8501A | 125-1930 | F87Z8501BA | 125-1840 |
| D1JJ8501C | 125-5012 | E2DZ8501A | 125-1210 | F1SZ8501B | 125-1630 | F87Z8501BB | 125-1840 |
| D1TZ8501A | 125-1740 | E3Z8501A | 125-1510 | F1TZ8501A | 125-1350 | F87Z8501CA | 125-1960 |
| D1TZ8501C | 125-2980 | E3BZ8501A | 125-1610 | F1VY8501A | 125-1750 | F8AZ8501AA | 125-1750 |
| D2Z8501A | 145-1100 | E3TZ8501C | 125-1340 | F2Z8501A | 125-5615 | F8AZ8501AA | 125-1820 |
| D2AZ8501A | 125-1410 | E3TZ8501E | 125-5060 | F2Z8501B | 125-1510 | F8DZ8501AA | 125-1820 |
| D2DZ8501A | 125-1380 | E3TZ8501F | 125-1310 | F2TZ8501A | 125-5640 | F8HZ8501B | 125-5062 |
| D2RY8501A | 125-1240 | E4Z8501B | 125-1520 | F2UZ8501A | 125-1760 | F8OZ8501AA | 125-5730 |
| D2SZ8501A | 125-1110 | E4Y8501A | 125-2020 | F2UZ8501C | 125-5750 | F8RZ8501B | 125-2100 |
| D2TZ8501A | 125-1740 | E4BZ8501A | 125-1610 | F3Z8501A | 145-1420 | F8RZ8501EN | 125-2100 |
| D2TZ8501B | 125-4057 | E4TZ8501ARM | 125-5720 | F3Z8501B | 145-1410 | F8RZ8501EN | 125-2100 |
| D2VY8501A | 125-1350 | E4TZ8501B | 125-1390 | F3Z8501A | 125-1510 | F8RZ8501ENE | 125-2100 |
| D2VY8501C | 125-1350 | E4TZ8501E | 125-1350 | F3DZ8501A | 125-5760 | F8RZ8501NE | 125-2100 |
| D3RY8501A | 125-1030 | E4ZZ8501A | 125-1560 | F3HZ8501ARM | 120-3072 | F8YZ8501AA | 125-9020 |
| D3RY8501B | 125-1240 | E4ZZ8501A | 125-1560 | F3HZ8501ARM | 125-5072 | F8YZ8501AA | 125-9020 |
| D3UZ8501A | 125-1420 | E4ZZ8501A | 125-1570 | F3LY8501A | 125-1830 | F8ZZ8501AA | 125-1940 |
| D3UZ8501A | 125-1440 | E5Z8501B | 125-1530 | F3LY8501B | 125-1830 | F0Z8501A | 145-1320 |
| D3UZ8501A | 125-1420 | E5HZ8501A | 125-5037 | F3TZ8501C | 125-1670 | XC2Z8501BA | 125-1980 |
| D4DZ8501A | 125-1290 | E5TZ8501A | 125-9010 | F3TZ8501E | 125-1810 | XF1Z8501AA | 125-1820 |
| D4FZ8501A | 145-1200 | E5TZ8501A | 125-5070 | F3XY8501B | 150-1360 | XF2Z8501AA | 125-1970 |
| D4TE8501C | 125-1390 | E5TZ8501C | 125-1350 | F3XY8501BA | 150-1360 | XF5Z8501AA | 150-2290 |
| D4TZ8501A | 125-4059 | E5ZZ8501A | 125-1560 | F4Z8501A | 145-1430 | XF5Z8501BA | 150-2290 |
| D4TZ8501B | 125-1370 | E5ZZ8501A | 125-1570 | F4AZ8501A | 125-1750 | XL3Z8501AA | 125-1980 |
| D4TZ8501C | 125-1390 | E6Z8501A | 125-1530 | F4AZ8501A | 125-1750 | XL3Z8501AA | 125-1980 |
| D4TZ8501D | 125-4103 | E6AZ8501A | 125-1560 | F4BZ8501B | 145-1310 | XL3Z8501BA | 125-5960 |
| D4TZ8501F | 125-4079 | E6DZ8501A | 125-1480 | F4CZ8501A | 125-1720 | XL5Z8501AA | 125-1850 |
| D4TZ8501G | 125-1430 | E6TZ8501A | 125-1580 | F4DZ8501A | 125-1790 | XL5Z8501CA | 125-1840 |
| D4TZ8501H | 125-1370 | E6ZZ8501A | 125-1610 | F4PZ8501A | 125-1480 | XR3Z8501AA | 125-5950 |
| D4TZ8501H | 125-1370 | E7FZ8501A | 125-1500 | F4SZ8501A | 125-1800 | XS2Z8501BC | 125-1910 |
| D4TZ8501K | 125-3083 | E7FZ8501B | 125-1520 | F4TZ8501ARM | 125-5720 | XS2Z8501CC | 125-1910 |
| D4TZ8501L | 125-4079 | E7GZ8501A | 145-1310 | F4TZ8501B | 125-5800 | XS2Z8501EA | 125-1910 |
| D4TZ8501M | 125-1430 | E7HZ8501B | 125-5062 | F4ZZ8501B | 125-1920 | XW4Z8501AA | 125-6030 |
| D4UZ8501A | 125-4052 | E7RY8501A | 125-5045 | F5Z8501A | 125-1850 | XW4Z8501BA | 125-5940 |
| D4VY8501A | 125-1350 | E7TZ8501A | 125-1670 | F5Z8501B | 125-1530 | YC2Z8501BA | 125-1980 |
| D4ZZ8501A | 125-1240 | E7TZ8501B | 125-1620 | F5DZ8501A | 125-1820 | YC2Z8501BA | 125-6050 |
| D4ZZ8501A | 125-1570 | E8AZ8501A | 125-1700 | F5DZ8501CL | 125-1950 | YC3Z8501AA | 125-5920 |
| D5BZ8501A | 125-1280 | E8AZ8501A | 125-1700 | F5HZ8501AA | 125-5037 | YF3Z8501AB | 125-5730 |
| D5DZ8501A | 125-1380 | E8BZ8501A | 125-1280 | F5RZ8501B | 125-1900 | YR3Z8501AB | 125-5950 |
| D5HZ8501F | 125-4093 | E8BZ8501A | 145-1310 | F5TZ8501A | 125-1810 | YS4Z8501AA | 125-5980 |
| D5NN8501E | 125-1200 | E8DZ8501B | 125-1600 | F5TZ8501BRM | 125-5720 | YS4Z8501AK | 125-6000 |
| D5RY8501A | 145-1200 | E8FZ8501A | 125-1500 | F5TZ8501BRM | 125-5721 | YW7Z8501AA | 125-1830 |
| D5TZ8501A | 125-1410 | E8HZ8501B | 125-5062 | F5TZ8501C | 125-1770 | YW7Z8501AA | 125-5970 |
| D5TZ8501B | 125-1390 | E8HZ8501B | 125-5062 | F5TZ8501CRM | 125-5720 | YW7Z8501AA | 125-1830 |
| D5TZ8501C | 125-1740 | E8SZ8501A | 125-1630 | F6Z8501AA | 125-1910 | YW7Z8501BB | 125-5970 |
| D5TZ8501E | 125-4096 | E9Z8501A | 125-1360 | F6Z8501AC | 125-2101 | | |
| D5TZ8501G | 125-1350 | E9BZ8501A | 145-1310 | F6Z8501BA | 125-1980 | General Motors | |
| D5UZ8501A | 125-1230 | E9DZ8501C | 125-5056 | F6Z8501A | 125-1970 | 230336 | 130-2773 |
| D5ZZ8501A | 125-3070 | E9JY8501B | 145-1350 | F6DZ8501B | 125-5870 | 230337 | 130-2926 |
| D6AZ8501A | 125-1110 | E9PZ8501A | 125-1340 | F6DZ8501FA | 125-1820 | 230337 | 130-2986 |
| D6HZ8501A | 125-5008 | E9PZ8501C | 125-1740 | F6JE8501BA | 125-5112 | 230608 | 130-2773 |
| D6ZZ8501A | 125-1230 | E9PZ8501D | 125-1390 | F6LZ8501AA | 125-1830 | 230899 | 130-2773 |
| D6ZZ8501B | 125-1230 | E9SZ8501B | 125-5055 | F6TZ8501AA | 125-5930 | 230900 | 130-2926 |

Water Pump Interchange List - OE Numbers

| Their No. | Our No. | Their No. | Our No. | Their No. | Our No. | Their No. | Our No. |
|-------------------------------|----------|-----------|----------|-----------|----------|-----------|----------|
| General Motors (Cont.) | | 3836083 | 130-1043 | 10089654 | 130-1470 | 12521037 | 130-1700 |
| 230900 | 130-2986 | 3836159 | 130-3563 | 10089659 | 130-1170 | 12521038 | 130-1320 |
| 231066 | 130-1360 | 3848071 | 130-2725 | 10112691 | 130-1340 | 12522016 | 130-1270 |
| 231073 | 130-1260 | 3876168 | 130-1010 | 10117819 | 130-6061 | 12522031 | 130-1620 |
| 231461 | 130-1360 | 3876168 | 130-2835 | 10120938 | 130-1120 | 12522032 | 130-1620 |
| 231462 | 130-1260 | 3876169 | 130-2725 | 10120943 | 130-1720 | 12522033 | 130-1250 |
| 231886 | 130-1250 | 3876171 | 130-2725 | 10120944 | 130-1600 | 12522034 | 130-1690 |
| 231886 | 130-1360 | 3876172 | 130-2986 | 10120945 | 130-1040 | 12522036 | 130-1790 |
| 231887 | 130-1260 | 3929219 | 130-1010 | 10132880 | 130-1600 | 12522036 | 130-1820 |
| 245788 | 130-2835 | 3929233 | 130-1350 | 10140667 | 130-6080 | 12523499 | 130-6074 |
| 327261 | 130-1010 | 3937996 | 130-1350 | 10159526 | 130-1050 | 12523502 | 130-7110 |
| 357261 | 130-1010 | 3947042 | 130-1010 | 10159599 | 130-7180 | 12524131 | 130-1250 |
| 357262 | 130-1340 | 3953620 | 130-1320 | 10174846 | 130-1690 | 12525123 | 130-1700 |
| 358937 | 130-2927 | 3957932 | 130-1270 | 10174858 | 130-1480 | 12527740 | 130-7110 |
| 359913 | 130-6900 | 3957981 | 130-1350 | 10174979 | 130-1510 | 12527741 | 130-7100 |
| 360155 | 130-1160 | 3957982 | 130-2981 | 10181235 | 130-1540 | 12527759 | 130-1700 |
| 361053 | 130-3088 | 3960122 | 130-2927 | 10181237 | 130-1540 | 12528917 | 130-1820 |
| 361054 | 130-1120 | 3977607 | 130-1320 | 10181325 | 130-1540 | 12529192 | 130-6080 |
| 361055 | 130-1160 | 3990991 | 130-1320 | 10181327 | 130-1540 | 12529305 | 130-1250 |
| 361055 | 130-1340 | 3990992 | 130-1410 | 10181369 | 130-1490 | 12529308 | 130-1320 |
| 372334 | 130-1250 | 3990993 | 130-2981 | 10448917 | 130-1250 | 12529993 | 130-1840 |
| 372334 | 130-1270 | 3998198 | 130-1270 | 12300305 | 130-1280 | 12530176 | 130-7200 |
| 388182 | 130-2773 | 3998205 | 130-1310 | 12309445 | 130-1280 | 12532526 | 130-1820 |
| 388183 | 130-2773 | 3998206 | 130-1330 | 12309978 | 130-1290 | 12532526 | 130-1820 |
| 424029 | 130-1250 | 3998206 | 130-1350 | 12321622 | 130-1400 | 12532528 | 130-1820 |
| 461996 | 130-1250 | 3998207 | 130-1330 | 12326453 | 130-1440 | 12532529 | 130-1620 |
| 474028 | 130-1270 | 3998207 | 130-1350 | 12334884 | 130-1450 | 12534417 | 130-1830 |
| 474029 | 130-1250 | 5123625 | 130-3074 | 12336298 | 130-1440 | 12534418 | 130-1330 |
| 474029 | 130-1270 | 5126877 | 130-3074 | 12336298 | 130-1590 | 12534772 | 130-7200 |
| 474055 | 130-1230 | 5135595 | 130-3074 | 12337519 | 130-1260 | 12536422 | 130-1590 |
| 474056 | 130-1340 | 5135596 | 130-3058 | 12337519 | 130-1360 | 12537417 | 130-1590 |
| 474079 | 130-1250 | 5562834 | 130-1260 | 12338842 | 130-1590 | 12537829 | 130-1780 |
| 478126 | 130-1280 | 6258119 | 130-2986 | 12350176 | 130-7200 | 12551474 | 130-6080 |
| 488377 | 130-1280 | 6258446 | 130-1010 | 12363169 | 130-1470 | 12556449 | 130-7340 |
| 491996 | 130-1250 | 6258548 | 130-1410 | 12369487 | 130-1620 | 12556449 | 130-7340 |
| 556283 | 130-1260 | 6258551 | 130-1310 | 12369537 | 130-7290 | 12558862 | 130-7260 |
| 1234772 | 130-7200 | 6260822 | 130-2985 | 12371989 | 130-1480 | 12558863 | 130-7090 |
| 1242913 | 130-1070 | 6272157 | 130-1250 | 12455105 | 130-7240 | 12560380 | 130-7340 |
| 1245288 | 130-1400 | 6272157 | 130-1270 | 12456113 | 130-7340 | 12560380 | 130-7340 |
| 1247079 | 130-1070 | 6272159 | 130-1320 | 12456113 | 130-7340 | 12561326 | 130-7280 |
| 1254131 | 130-1250 | 7490004 | 130-1850 | 12456231 | 130-1250 | 12562458 | 130-7340 |
| 1257703 | 130-1070 | 7490007 | 130-1840 | 12456231 | 130-7250 | 12562458 | 130-7340 |
| 1260709 | 130-1070 | 8875385 | 130-2835 | 12456263 | 130-7250 | 12566029 | 130-5130 |
| 1389590 | 130-9590 | 8885837 | 130-2835 | 12456326 | 130-1700 | 12585226 | 130-7350 |
| 1394877 | 130-1400 | 8885838 | 130-6005 | 12458115 | 130-7240 | 12591894 | 130-7350 |
| 1394926 | 130-1430 | 8885937 | 130-2835 | 12458934 | 130-1590 | 14029998 | 130-1030 |
| 1396317 | 130-1420 | 8889420 | 130-7340 | 12458934 | 130-7290 | 14058915 | 130-5019 |
| 1396346 | 130-1420 | 9772372 | 130-2850 | 12458935 | 130-7260 | 14063641 | 130-1210 |
| 1396715 | 130-1420 | 9777913 | 130-2850 | 12458935 | 130-7340 | 14079351 | 130-1030 |
| 1396758 | 130-9590 | 9793130 | 130-2850 | 12462265 | 130-1470 | 14085847 | 130-1250 |
| 1396876 | 130-1420 | 9797581 | 130-2912 | 12482714 | 130-1860 | 14085852 | 130-1320 |
| 1396879 | 130-2821 | 10004073 | 130-1050 | 12482714 | 130-7130 | 14087581 | 130-2981 |
| 1396880 | 130-2821 | 10004073 | 130-1051 | 12482903 | 130-1780 | 14089011 | 130-1510 |
| 2235969 | 130-6005 | 10032022 | 130-1520 | 12482919 | 130-1590 | 14101304 | 130-1040 |
| 2340256 | 130-3669 | 10039415 | 130-1490 | 12487361 | 130-1840 | 14105921 | 130-1170 |
| 2384340 | 130-6005 | 10039422 | 130-1490 | 12507232 | 130-1050 | 14120945 | 130-1040 |
| 2384840 | 130-6005 | 10042949 | 130-1050 | 12507232 | 130-1051 | 15633465 | 130-1330 |
| 2417197 | 130-2835 | 10046305 | 130-1230 | 12507232 | 130-1740 | 15633466 | 130-1830 |
| 2475788 | 130-2835 | 10048917 | 130-1250 | 12508606 | 130-1610 | 21006933 | 130-1800 |
| 3633088 | 130-2851 | 10048919 | 130-1220 | 12509653 | 130-6073 | 21007453 | 130-1810 |
| 3633853 | 130-1290 | 10048921 | 130-1310 | 12512740 | 130-6080 | 21007655 | 130-1800 |
| 3634514 | 130-1290 | 10048949 | 130-1480 | 12514574 | 130-1830 | 21015340 | 130-1800 |
| 3634580 | 130-1370 | 10048950 | 130-1720 | 12514594 | 130-1830 | 22514839 | 130-1240 |
| 3634789 | 130-6023 | 10049026 | 130-1270 | 12517379 | 130-1110 | 22519584 | 130-1200 |
| 3634838 | 130-1370 | 10049817 | 130-1250 | 12517940 | 130-1700 | 22519854 | 130-1200 |
| 3636801 | 130-6023 | 10054510 | 130-1040 | 12518277 | 130-7100 | 23500133 | 130-1330 |
| 3741033 | 130-3563 | 10065240 | 130-1060 | 12518295 | 130-1480 | 24439798 | 125-7350 |
| 3757231 | 130-3563 | 10074182 | 130-1390 | 12518443 | 130-1470 | 24439798 | 130-7350 |
| 3774186 | 130-3563 | 10077051 | 130-1030 | 12520263 | 130-1390 | 24461382 | 130-7350 |
| 3789536 | 130-3669 | 10077059 | 130-1620 | 12520263 | 130-6080 | 24467301 | 130-7350 |
| 3815726 | 130-1010 | 10081980 | 130-1700 | 12520914 | 130-1750 | 24570464 | 130-1660 |

Water Pump Interchange List - OE Numbers

| Their No. | Our No. | Their No. | Our No. | Their No. | Our No. | Their No. | Our No. |
|-------------------------------|----------|----------------|----------|----------------|----------|-------------------------------|----------|
| General Motors (Cont.) | | 94856254 | 170-1830 | 19200PK2000 | 135-1290 | 2510039800 | 146-1240 |
| 24571389 | 130-1660 | 94858649 | 170-1980 | 19200PLMA01 | 135-2420 | 2510039802 | 146-1240 |
| 24573636 | 130-7130 | 94858708 | 170-1860 | 19200PM3013 | 135-1260 | 2510039802 | 146-1240 |
| 24575951 | 130-7130 | 96054298 | 165-1080 | 19200PM3014 | 135-1260 | 2510041000 | 148-1330 |
| 24576875 | 130-7130 | 96059659 | 165-1160 | 19200PNA003 | 135-1520 | 2510041000 | 148-1330 |
| 24576952 | 130-7700 | 96060136 | 165-1150 | 19200PNLE01 | 135-1520 | 2510041001 | 148-1330 |
| 24577255 | 130-1860 | 96062832 | 165-1160 | 19200PNLE01 | 135-1520 | 2510041001 | 148-1330 |
| 24577255 | 130-7130 | 96067153 | 165-1150 | 19200PO1004 | 135-1260 | 2510045100 | 148-1330 |
| 25514839 | 130-1240 | 97031472 | 140-1330 | 19200PT0013 | 135-1280 | 2510045100 | 148-1330 |
| 25519584 | 130-1201 | 97216136 | 130-5980 | 19200RAAA01 | 135-1500 | | |
| 25525147 | 130-1450 | 29300332806 | 110-3021 | 19200RAAA01 | 135-1520 | Infiniti | |
| 25527536 | 130-1070 | 29300733473 | 138-1010 | 19200RAD003 | 135-1500 | 2101002P27 | 150-1280 |
| 25527537 | 130-1440 | 29308485960 | 130-1010 | 19200RAD003 | 135-1520 | 210100P526 | 150-2215 |
| 52273124 | 130-1110 | 29309318084 | 138-3776 | 19200RAD003 | 135-1520 | 210100P527 | 150-2215 |
| 55352002 | 158-2020 | 29309834192 | 120-1060 | 19200RCAA01 | 135-1530 | 210100W025 | 150-1610 |
| 88893906 | 130-7260 | 29309979833 | 130-2986 | 19200RDMA01 | 135-1530 | 210100W027 | 150-1610 |
| 88893907 | 130-7090 | 2930V990006 | 110-2986 | 19210PCX003 | 135-2410 | 210101P127 | 150-2280 |
| 88893907 | 130-7250 | 2930V990021 | 120-1060 | 19210PHM010 | 135-6920 | 210101P128 | 150-2280 |
| 88894035 | 130-7250 | 2930V990025 | 110-2843 | 19210PHM010 | 135-6920 | 2101031U25 | 150-1510 |
| 88894035 | 130-7250 | 2930V990029 | 130-1010 | 19210PHM010 | 135-2400 | 2101031U26 | 150-1510 |
| 88894044 | 130-1830 | 2930V990035 | 130-2986 | 8970812800 | 140-1340 | 2101031U27 | 150-1510 |
| 88894290 | 130-7340 | 2930V990039 | 125-1380 | 8970816230 | 140-1310 | 2101031U28 | 150-1510 |
| 88894290 | 130-7340 | 8888942900 | 130-7340 | 8971259750 | 140-1340 | 2101031U29 | 150-1510 |
| 88894344 | 130-1840 | 8888942900 | 130-7340 | 8971655540 | 140-1440 | 2101053J00 | 150-1480 |
| 88894345 | 130-7290 | | | | | 2101053J03 | 150-1480 |
| 88972167 | 130-7360 | Henry J | | Hummer | | 2101053J04 | 150-1480 |
| 88972819 | 170-2400 | 208915 | 110-1052 | 5740079 | 130-1330 | 2101060U25 | 150-2210 |
| 89017315 | 130-7340 | | | 5743241 | 130-1830 | 2101067U25 | 150-2270 |
| 89017315 | 130-7340 | Honda | | 5743939 | 130-1620 | 2101067U26 | 150-2270 |
| 89017439 | 130-7340 | 19110634671 | 135-6910 | 5744662 | 130-7200 | 210107S000 | 150-9010 |
| 89017439 | 130-7340 | 19110634671 | 135-6910 | 5745093 | 130-7250 | 210107S000 | 150-9010 |
| 89017439 | 130-7341 | 19110634335 | 135-1131 | 89017439 | 130-7341 | 21010AL525 | 150-2320 |
| 89017456 | 130-7290 | 19110657335 | 135-1151 | | | 21010AL526 | 150-2320 |
| 89017467 | 130-1840 | 19110671335 | 135-1161 | Hysler | | 21010AL527 | 150-2320 |
| 89017593 | 130-7290 | 19110673335 | 135-1161 | 1361811 | 145-1230 | 251007S000 | 150-9010 |
| 89017693 | 130-7260 | 19110689335 | 135-1161 | 2022312 | 145-1290 | 251007S000 | 150-9010 |
| 89017694 | 130-7090 | 19200634335 | 135-1131 | 93432783 | 196-2069 | | |
| 89017748 | 130-1820 | 19200657010 | 135-1161 | D3JL8501C | 125-5009 | International/Navistar | |
| 90220568 | 130-1610 | 19200671335 | 135-1161 | | | 170027R91 | 138-3776 |
| 90392900 | 130-1460 | 19200673000 | 135-1161 | Hyundai | | 1700594C91 | 138-4702 |
| 90392901 | 155-1130 | 19200689335 | 135-1100 | 2510011010 | 148-1010 | 1805951C91 | 138-4705 |
| 90392902 | 130-1610 | 19200P08004 | 135-1320 | 2510021000 | 148-1170 | 1805952C91 | 138-4705 |
| 90392908 | 130-1110 | 19200P0A001 | 135-1280 | 2510022010 | 148-1170 | 1809374C91 | 138-4705 |
| 90537805 | 130-7350 | 19200P0A003 | 135-1280 | 2510022012 | 148-1170 | 1809374C94 | 138-4705 |
| 90543277 | 158-2020 | 19200P0BA01 | 135-1280 | 2510022650 | 148-1170 | 1815538C91 | 138-4712 |
| 91172178 | 165-1160 | 19200P0GA01 | 135-1250 | 2510023001 | 146-2020 | 1817687C94 | 138-4713 |
| 91173189 | 165-1150 | 19200P10A02 | 135-1260 | 2510023002 | 146-2020 | 1817687C96 | 138-4713 |
| 91173496 | 165-1160 | 19200P13000 | 135-1330 | 2510023010 | 146-2020 | 1823669C92 | 138-3669 |
| 91174230 | 165-1230 | 19200P13003 | 135-1330 | 2510023020 | 146-2020 | 1823669C92 | 138-3669 |
| 91174230 | 165-2050 | 19200P14A00 | 135-1340 | 2510024030 | 148-1170 | 270918C92 | 138-1010 |
| 91174494 | 165-2001 | 19200P2AA01 | 135-1390 | 2510024060 | 148-1170 | 297359C93 | 138-4031 |
| 91174494 | 165-2060 | 19200P2J005 | 135-1490 | 2510026015 | 146-1230 | 303395R91 | 138-4703 |
| 91175666 | 165-1150 | 19200P2J005 | 135-1490 | 2510026660 | 146-2070 | 3132676R93 | 138-4708 |
| 91176170 | 165-2070 | 19200P2J005 | 135-1490 | 2510026900 | 146-2070 | 3136217R92 | 196-2059 |
| 94022627 | 140-1140 | 19200P30003 | 135-2200 | 2510026901 | 146-2070 | 355760R93 | 196-2011 |
| 94105354 | 140-2366 | 19200P72013 | 135-2210 | 2510032510 | 148-1270 | 357621C92 | 138-4126 |
| 94109591 | 140-1300 | 19200P72013 | 135-6800 | 2510033012 | 146-1080 | 357621C93 | 138-4126 |
| 94118501 | 130-1530 | 19200P75003 | 135-1400 | 2510033111 | 148-1440 | 368496R91 | 138-4703 |
| 94136076 | 140-1190 | 19200P8AA02 | 135-2380 | 2510033112 | 148-1440 | 387038C91 | 110-2843 |
| 94202477 | 140-1010 | 19200P8AA03 | 135-2380 | 2510033132 | 148-1440 | 433361C91 | 110-2986 |
| 94224894 | 140-1010 | 19200PA0000 | 135-1070 | 25100335010 | 148-1400 | 445306C91 | 110-1040 |
| 94239153 | 130-1190 | 19200PA1000 | 135-6900 | 2510035020 | 148-1400 | 448087C92 | 138-4704 |
| 94239649 | 140-1200 | 19200PA1000 | 135-1110 | 2510035030 | 148-1400 | 463365C91 | 138-1010 |
| 94240378 | 140-1190 | 19200PA6000 | 135-1080 | 2510035040 | 148-1400 | 601816C92 | 138-4703 |
| 94331664 | 140-1330 | 19200PC1000 | 135-1080 | 2510037102 | 146-2040 | 673162C94 | 138-4707 |
| 94360200 | 140-1320 | 19200PD2660 | 135-1210 | 2510037200 | 146-2040 | 673162C94 | 138-4709 |
| 94840612 | 170-1580 | 19200PD6000 | 135-1210 | 2510037201 | 146-2040 | 673623C92 | 138-4706 |
| 94844775 | 170-1630 | 19200PE0010 | 135-1220 | 2510038000 | 146-1110 | 680899C93 | 138-4709 |
| 94847609 | 170-1580 | 19200PE0660 | 135-1220 | 2510038002 | 146-1110 | 685155C95 | 138-4710 |
| 94854103 | 170-1860 | 19200PH1505 | 135-1230 | 2510039010 | 146-1130 | 861236R92 | 138-1010 |
| 94854791 | 170-1830 | 19200PH3000 | 135-1300 | 2510039800 | 146-1240 | | |

Water Pump Interchange List - OE Numbers

| Their No. | Our No. | Their No. | Our No. | Their No. | Our No. | Their No. | Our No. |
|--------------|----------|---------------|----------|-----------------|----------|-------------------|----------|
| Isuzu | | 8890174390 | 130-7340 | EBC8550 | 113-2090 | 2510037201 | 146-2040 |
| 5131610121 | 140-1150 | 8920642500 | 140-2400 | EBC8560 | 113-2070 | 2510038002 | 146-1110 |
| 5131610121 | 140-1150 | 8920659690 | 140-2400 | GWP415 | 113-1120 | 2510038200 | 146-1110 |
| 5136100120 | 140-1150 | 8941095911 | 140-1300 | GWP423 | 113-1130 | 2510039010 | 146-1130 |
| 5136100120 | 140-1150 | 8941185010 | 130-1530 | JLM10819 | 113-2100 | 251003X000 | 146-2110 |
| 5136100121 | 140-1150 | 8941207680 | 140-1200 | JLM1330 | 113-2100 | OFE1H15010G | 145-1320 |
| 5136100121 | 140-1150 | 8941313301 | 140-2040 | JLM20143 | 125-6030 | OFE1H15010H | 145-1320 |
| 5136100122 | 140-1150 | 8941463260 | 140-1220 | JLM20143 | 125-6030 | OFE3N15010E | 143-1190 |
| 5136100122 | 140-1150 | 8941769890 | 140-1160 | JLM20579 | 125-6030 | OK24715010B | 143-2001 |
| 5136100123 | 140-1150 | 8941769890 | 140-1160 | JLM20579 | 125-6030 | OK24A15010 | 143-1170 |
| 5136100123 | 140-1150 | 8941769891 | 140-1160 | JLM206 | 113-1130 | OK93015010A | 145-1310 |
| 5136100470 | 140-1430 | 8941769891 | 140-1160 | JLM20915 | 125-6030 | | |
| 5136100470 | 140-1430 | 8941769892 | 140-1160 | JLM20915 | 125-6030 | Komatsu | |
| 513610047Z | 140-1430 | 8941769892 | 140-1160 | JLM2097 | 113-2100 | 2101013226 | 150-1010 |
| 513610047Z | 140-1430 | 8942024771 | 140-1010 | JLM398 | 113-1120 | 2101019225 | 150-2505 |
| 5136100570 | 140-1430 | 8942248940 | 140-1010 | NBB2200DA | 113-2070 | 2101048302 | 150-2500 |
| 5136100570 | 140-1430 | 8942323470 | 140-1192 | XR813290 | 125-5940 | 2101048303 | 150-2500 |
| 513610057Z | 140-1430 | 8942403780 | 140-1190 | XR815090 | 125-6040 | 2101061527 | 150-1530 |
| 513610057Z | 140-1430 | 8943326360 | 140-2090 | XR815090 | 125-6040 | 2101078226 | 150-1060 |
| 5136100772 | 140-1430 | 8943326370 | 140-1220 | | | 21010J5125 | 150-1060 |
| 5136100772 | 140-1430 | 8943768430 | 140-1160 | Jeep/AMC | | 21010L1125 | 150-1300 |
| 5136100772 | 140-1430 | 8943768430 | 140-1160 | 4626054 | 110-1090 | | |
| 513610077Z | 140-1430 | 8943768431 | 140-1160 | 53020280 | 120-3041 | Lancia | |
| 5136101500 | 140-1160 | 8943768431 | 140-1160 | 83500807 | 130-1170 | 4331825 | 123-1030 |
| 5136101500 | 140-1160 | 8943768630 | 140-1430 | 83502938 | 110-1060 | | |
| 5136101501 | 140-1160 | 8943768630 | 140-1430 | 83502957 | 110-1070 | Land Rover | |
| 5136101501 | 140-1160 | 8943768631 | 140-1430 | 83503407 | 110-1080 | 269485 | 144-2009 |
| 5136101502 | 140-1160 | 8943768631 | 140-1430 | 05012366AD | 120-4340 | 269845 | 144-2009 |
| 5136101502 | 140-1160 | 894376863Z | 140-1430 | 4626054AD | 110-1090 | 501039 | 144-2011 |
| 5136101630 | 140-1430 | 894376863Z | 140-1430 | 4626215AD | 110-1080 | 530478 | 144-2006 |
| 5136101630 | 140-1430 | 8944370481 | 140-2060 | 4694307AB | 120-4220 | 568314 | 144-2007 |
| 513610163Z | 140-1430 | 8944398501 | 140-1350 | 4694307AC | 120-4220 | 602298 | 144-2008 |
| 513610163Z | 140-1430 | 8944831670 | 140-1430 | 5012366AA | 120-4340 | 614203 | 144-2010 |
| 5136101691 | 140-1430 | 8944831670 | 140-1430 | 5012366AC | 120-4340 | STC1610 | 144-2004 |
| 5136101691 | 140-1430 | 8944831671 | 140-1430 | 53020873AC | 120-4350 | STC1693 | 144-2001 |
| 5136101692 | 140-1430 | 8944831671 | 140-1430 | 53021018AB | 120-3041 | STC4378 | 144-2005 |
| 5136101692 | 140-1430 | 894483167Z | 140-1430 | 53021187AA | 120-4350 | STC4434 | 144-2003 |
| 5136101693 | 140-1430 | 894483167Z | 140-1430 | J0649717 | 110-1052 | STC483 | 144-2000 |
| 5136101693 | 140-1430 | 8970214730 | 140-1320 | J0945142 | 110-1111 | STC486 | 144-2002 |
| 5136101694 | 140-1430 | 8970217731 | 140-1220 | J0948681 | 130-1420 | | |
| 5136101694 | 140-1430 | 8970217740 | 140-1310 | J0994149 | 130-1420 | Lexus | |
| 513610169Z | 140-1430 | 8970217741 | 140-1310 | J3205620 | 110-3021 | 1610009070 | 170-1920 |
| 513610169Z | 140-1430 | 8970285950 | 140-1430 | J3227694 | 110-1040 | 1610029085 | 170-1920 |
| 5136101700 | 140-1430 | 8970285950 | 140-1430 | J3234427 | 110-1040 | 1610049115 | 170-2270 |
| 5136101700 | 140-1430 | 897028595Z | 140-1430 | J8120130 | 110-2908 | 1610049116 | 170-2270 |
| 5136101701 | 140-1430 | 897028595Z | 140-1430 | J8120131 | 110-3021 | 1610049835 | 170-2270 |
| 5136101701 | 140-1430 | 8970314720 | 140-1330 | J8120999 | 110-2052 | 1610049836 | 170-2270 |
| 5136101702 | 140-1430 | 8970314730 | 140-1320 | J8125131 | 110-1040 | 1610049875 | 170-2380 |
| 5136101702 | 140-1430 | 8970612800 | 140-1340 | J8125501 | 110-1010 | 1610050020 | 170-1840 |
| 5136101703 | 140-1430 | 8970816230 | 140-1310 | J8126774 | 110-2052 | 1610050022 | 170-1840 |
| 5136101703 | 140-1430 | 8971259750 | 140-1340 | J8130749 | 110-1030 | 1610050030 | 170-1840 |
| 513610170Z | 140-1430 | 8971675540 | 140-1440 | J8132274 | 130-1120 | 1610059275 | 170-1840 |
| 513610170Z | 140-1430 | 9136101050 | 140-1140 | J8133033 | 110-1030 | 1610069206 | 170-1710 |
| 5136101870 | 140-1160 | 9136103192 | 140-1130 | J8133034 | 110-1050 | 1610069325 | 170-1990 |
| 5136101870 | 140-1160 | 9136103250 | 140-1430 | J8134320 | 110-1030 | 1610069335 | 170-1710 |
| 5136161690 | 140-1430 | 9136103250 | 140-1430 | J8134321 | 110-1050 | 1611049116 | 170-2270 |
| 5136161690 | 140-1430 | 913610325Z | 140-1430 | T1461336 | 110-3075 | 1611049155 | 170-2380 |
| 513616169Z | 140-1430 | 913610325Z | 140-1430 | | | 1611049156 | 170-2380 |
| 513616169Z | 140-1430 | 9136103940 | 140-1430 | Kalmar | | | |
| 586103073Z | 150-1540 | 9136103940 | 140-1430 | 4921313 | 148-1260 | Mack Truck | |
| 586103073Z | 150-1540 | 913610394Z | 140-1430 | | | 316GC1184BX | 196-2004 |
| 5862023750 | 135-1280 | 913610394Z | 140-1430 | Kia | | 316GC1210A | 196-2046 |
| 8101209430 | 130-1720 | 9136176080 | 140-1150 | 024715010B | 143-2001 | 316GC1210AX | 196-2046 |
| 8123631690 | 130-1470 | 9136176080 | 140-1150 | 024A15010 | 143-1170 | 316GC1211AX | 196-2004 |
| 8124589280 | 130-1790 | TK4576 | 140-1270 | OK24715010A | 143-2001 | 316GC1219 | 196-2046 |
| 8124622650 | 130-1470 | Z5136100570 | 140-2500 | OK24715010B | 143-2001 | 316GCA1211 | 196-2004 |
| 8125184430 | 130-1470 | | | OK30E15010 | 146-2003 | 316GCA1211A | 196-2004 |
| 8125244980 | 130-1790 | Jaguar | | 2510023021 | 146-2020 | 316GCA184C | 196-2006 |
| 8125325280 | 130-1820 | AJ84817 | 125-6040 | 251002X401 | 146-2003 | 316GCA184D | 196-2006 |
| 8245769520 | 130-7700 | EBC10967 | 113-2120 | 2510037102 | 146-2040 | 316GCA184E | 196-2006 |
| 8888942900 | 130-7340 | EBC4437 | 113-2090 | 2510037200 | 146-2040 | 316GCA184F | 196-2006 |

Water Pump Interchange List - OE Numbers

| Their No. | Our No. | Their No. | Our No. | Their No. | Our No. | Their No. | Our No. |
|------------------------|----------|--------------|----------|-------------------|----------|---------------|----------|
| Massey Ferguson | | 175723925B | 145-1180 | ZZM715010 | 125-1850 | MD997244 | 148-1400 |
| 947544 | 120-2713 | 1F0015010 | 125-1840 | ZZPO15010A | 125-1840 | MD997465 | 148-1240 |
| 3420050 | 120-1060 | 1F2215010 | 125-2102 | ZZR115010 | 125-1850 | MD997609 | 148-1170 |
| 3947051 | 130-2986 | 232915130A | 145-1110 | | | MD997615 | 148-1230 |
| 3957981 | 130-1350 | 3M4Z8501BJ | 145-2510 | Mercuriser | | MD997616 | 148-1370 |
| 1022115M91 | 120-1060 | 3M4Z8501BJ | 145-2510 | 814755 | 130-6059 | MD997619 | 148-1190 |
| 1025282M91 | 130-3669 | 6012000920 | 147-2160 | 65142A1 | 130-6059 | MD997620 | 148-1530 |
| 1032473M91 | 130-1350 | 6022000020 | 147-2065 | | | MD997623 | 148-2130 |
| 1035836M91 | 130-1350 | 6022000220 | 147-2065 | MG | | MD997634 | 148-1400 |
| 1039163M91 | 120-1060 | 887215010B | 145-1180 | 2A774 | 113-1010 | MD997643 | 148-1500 |
| 1501926M91 | 120-2713 | 8AB415010 | 145-1310 | GWP102 | 113-1010 | MO4667660 | 120-1300 |
| 1504002M91 | 120-2713 | 8AB515010 | 145-1350 | GWP114 | 113-2050 | | |
| 735036M91 | 196-2019 | 8AB715010 | 145-1310 | GWP115 | 113-2060 | Morris | |
| 830691M91 | 196-2007 | 8AB815010 | 145-1350 | GWP115 | 113-2140 | GWP101 | 113-1010 |
| 830862M91 | 196-2009 | 8ABB15010 | 145-1390 | GWP123 | 113-1050 | | |
| 8530514M91 | 196-2007 | 8ABB150101 | 145-1390 | P111 | 113-2040 | Nissan | |
| | | 8ABB15010A | 145-1390 | UKC774 | 113-2080 | 2101002P27 | 150-1280 |
| | | 8ABE15010 | 145-2250 | | | 2101003J25 | 150-1450 |
| Mazda | | 8AD215010 | 145-1310 | Mini | | 2101003J25 | 150-1450 |
| 1812001201 | 196-2040 | 8AE215010 | 145-1420 | 11517520123 | 148-1780 | 2101003J26 | 150-1450 |
| 030515010C | 145-1020 | 8AF215010 | 145-1330 | 11517520123 | 148-1780 | 2101003J26 | 150-1450 |
| 030515010D | 145-1020 | 8AF315010 | 145-1330 | | | 2101005H00 | 150-2504 |
| 032415010A | 145-1030 | 8AF415010 | 145-1330 | Mitsubishi | | 2101006E26 | 150-1350 |
| 032415010C | 145-1030 | 8AF415100 | 145-1330 | 1300A011 | 148-2320 | 2101009W25 | 150-1190 |
| 032415010D | 145-1030 | 8AF415100 | 145-1330 | 1300A011 | 148-2320 | 210100M300 | 150-1420 |
| 038115010A | 145-1100 | 8AFB15010 | 145-2070 | 2510021000 | 148-1170 | 210100W025 | 150-1610 |
| 045915010A | 145-1190 | 8AFC15010 | 145-2070 | MD001300 | 148-1010 | 210100W027 | 150-1610 |
| 055215010G | 145-1140 | 8AFD15010 | 145-2070 | MD009000 | 148-1120 | 210100Z800 | 150-1500 |
| 1022000120 | 147-2080 | 8AG115010A | 145-1290 | MD011300 | 148-1020 | 2101010G25 | 150-1370 |
| 1022005001 | 147-2061 | 8AG915010 | 145-1410 | MD019461 | 148-1300 | 2101010G25 | 150-1370 |
| 1032002601 | 147-2063 | 8AH215010A | 145-1320 | MD019461 | 148-1300 | 2101010G26 | 150-1370 |
| 1032003701 | 147-2063 | 8AH315010C | 145-1360 | MD021490 | 148-1130 | 2101010G26 | 150-1370 |
| 1042000801 | 147-2070 | 8AH615010 | 145-2130 | MD025475 | 148-1260 | 2101012G26 | 150-1410 |
| 1042002801 | 147-2090 | 8AH715010 | 145-2125 | MD179030 | 148-1470 | 2101013201 | 150-1010 |
| 1042002801 | 147-2170 | 8AK115010 | 145-1320 | MD300799 | 148-1470 | 2101013226 | 150-1010 |
| 1042003001 | 147-2190 | 8AK215010 | 145-1430 | MD306414 | 148-1470 | 2101016A85 | 150-1260 |
| 1042003101 | 147-2070 | 8AK315010 | 145-2160 | MD309756 | 148-2280 | 2101016E02 | 150-1360 |
| 1042003101 | 147-2070 | 8AL115010B | 145-1380 | MD323372 | 148-1540 | 2101016E03 | 150-1360 |
| 1042003201 | 147-2100 | 8AL415010 | 145-1480 | MD346789 | 148-2300 | 2101017C28 | 150-2230 |
| 1042003301 | 147-2090 | 8AL415010A | 145-1480 | MD365087 | 148-1540 | 2101017S27 | 150-1160 |
| 1042003301 | 147-2110 | 8BU115010 | 148-1370 | MD972003 | 148-1400 | 210101E400 | 150-1500 |
| 1042004501 | 147-2180 | A3662000601 | 196-2058 | MD972004 | 148-1400 | 210101E401 | 150-1500 |
| 1042004601 | 147-2240 | A3662000923 | 196-2058 | MD972005 | 148-1500 | 2101021028 | 150-1030 |
| 1042004901 | 147-2180 | A3662000923L | 196-2067 | MD972050 | 148-1480 | 2101022P25 | 150-2150 |
| 1102000220 | 147-2065 | A3662006801 | 196-2067 | MD972052 | 148-1440 | 2101023028 | 150-1123 |
| 1102000920 | 147-1020 | AJ0315010 | 145-2510 | MD972053 | 148-1450 | 2101030R05 | 150-1430 |
| 1102001020 | 147-2050 | AJ0315010 | 145-2510 | MD972440 | 148-1600 | 2101031U25 | 150-1510 |
| 1102001720 | 147-1020 | AJ0315010A | 145-2510 | MD972934 | 148-1610 | 2101031U26 | 150-1510 |
| 1112000401 | 147-2120 | AJ0315010A | 145-2510 | MD973025 | 148-1510 | 2101031U27 | 150-1510 |
| 1112002301 | 147-2260 | AJ0315010G | 125-6060 | MD973162 | 148-1510 | 2101031U29 | 150-1510 |
| 1122000401 | 147-2220 | AJ5715010A | 145-2510 | MD976464 | 148-2330 | 2101031U85 | 150-1510 |
| 1122000501 | 147-2250 | AJ5715010A | 145-2510 | MD976943 | 148-2330 | 2101031W26 | 150-1190 |
| 1122001101 | 147-2170 | AJ5715010B | 145-2510 | MD977503 | 148-1790 | 2101037528 | 150-1100 |
| 1122001401 | 147-2220 | AJ5715010B | 145-2510 | MD977705 | 148-1510 | 2101037726 | 150-1010 |
| 1122001501 | 147-2250 | E30115010A | 145-1210 | MD978552 | 148-1810 | 2101037726 | 150-1100 |
| 1122002101 | 147-2210 | F80115010B | 145-1250 | MD978741 | 148-1510 | 2101040F25 | 150-1400 |
| 1142002801 | 147-2100 | FE7915010C | 145-1290 | MD978743 | 148-2320 | 2101048305 | 150-2500 |
| 1152000320 | 147-1010 | FP0115010 | 145-1410 | MD979171 | 148-1790 | 210104M525 | 150-1730 |
| 1152000920 | 147-1020 | GY0115010B | 125-1910 | MD979313 | 148-1780 | 210104S100 | 150-1610 |
| 1152001620 | 147-1010 | LF0115100 | 125-6000 | MD979395 | 148-1780 | 210104S125 | 150-1610 |
| 1162001601 | 147-2010 | LF5215100 | 125-6000 | MD980000 | 148-1400 | 210104S126 | 150-1610 |
| 1162001701 | 147-2010 | N23299153A | 145-1180 | MD997074 | 148-1300 | 2101050A27 | 150-1240 |
| 1172000201 | 147-1030 | N3A115010A | 145-2135 | MD997074 | 148-1300 | 2101050A89 | 150-1240 |
| 1172000301 | 147-1030 | RF0199154 | 125-1520 | MD997078 | 148-1190 | 2101052600 | 150-1080 |
| 1172002901 | 147-2140 | S21315010B | 145-2010 | MD997079 | 148-1230 | 2101052600 | 150-1080 |
| 1192001501 | 147-2130 | YF0915100 | 125-2100 | MD997081 | 148-1270 | 2101053J00 | 150-1480 |
| 1192001501 | 147-2140 | ZL0115010 | 145-1390 | MD997082 | 148-1130 | 2101053J03 | 150-1480 |
| 1192002101 | 147-2210 | ZZL015010 | 125-1770 | MD997124 | 148-1350 | 2101053J04 | 150-1480 |
| 1202001101 | 147-2170 | ZZM015010 | 125-1610 | MD997124 | 148-1350 | 2101053Y01 | 150-1420 |
| 1212000320 | 147-1010 | ZZM115010 | 125-1530 | MD997150 | 148-1390 | 2101055100 | 150-1080 |
| 1212000920 | 147-1020 | ZZM315010 | 125-1840 | MD997178 | 148-1370 | 2101055100 | 150-1080 |
| 1272000220 | 147-1010 | ZZM515010 | 125-1770 | | | | |
| 162015130C | 145-1160 | | | | | | |

Water Pump Interchange List - OE Numbers

| Their No. | Our No. | Their No. | Our No. | Their No. | Our No. | Their No. | Our No. |
|-----------------------|----------|-----------------------|----------|------------------|----------|-------------------|----------|
| Nissan (Cont.) | | 2108236W00 | 150-1162 | 1202.85 | 156-2030 | Sterling | |
| 2101057J00 | 150-1520 | 21082H7200 | 150-1112 | 1202.87 | 156-1060 | 26526500010 | 135-1250 |
| 2101057J00 | 150-1520 | 21082H9100 | 150-1112 | 1202.87 | 156-2040 | | |
| 2101057J01 | 150-1520 | 21082V0700 | 150-1162 | 1206.60 | 156-1010 | Studebaker | |
| 2101057J01 | 150-1520 | 21082Y7001 | 150-1162 | 120298 | 156-9010 | 1564459 | 130-1350 |
| 2101057J02 | 150-1520 | 251007S000 | 150-9010 | 120298 | 156-9010 | 1565487 | 130-1350 |
| 2101057J02 | 150-1520 | 251007S000 | 150-9010 | | | | |
| 2101057J03 | 150-1520 | | | Porsche | | Subaru | |
| 2101057J03 | 150-1520 | Oliver Tractor | | 99610601153 | 180-9030 | 21110AA015 | 160-1130 |
| 2101057J25 | 150-1520 | 5135595 | 130-3074 | 99610601153 | 180-9030 | 21110AA016 | 160-1130 |
| 2101057J25 | 150-1520 | 5186575 | 130-3074 | 99610601154 | 180-9030 | 21110AA025 | 160-1140 |
| 2101057J26 | 150-1520 | | | 99610601154 | 180-9030 | 21110AA040 | 160-1010 |
| 2101057J26 | 150-1520 | OMC | | 060121011 | 180-1040 | 21110AA040 | 160-1050 |
| 2101058000 | 150-1080 | 982517 | 125-5074 | 92810601520 | 180-2150 | 21110AA050 | 160-1030 |
| 2101058000 | 150-1080 | 984360 | 130-6059 | 92810601520 | 180-2160 | 21110AA050 | 160-1040 |
| 2101058001 | 150-1080 | 984876 | 125-5073 | 92810601522 | 180-2160 | 21110AA060 | 160-1030 |
| 2101058001 | 150-1080 | 984889 | 125-5075 | 94410600300 | 180-2180 | 21110AA070 | 160-1060 |
| 2101058025 | 150-1080 | 985429 | 130-6060 | 94410602110 | 180-2110 | 21110AA110 | 160-2055 |
| 2101058025 | 150-1080 | 986779 | 130-6059 | 94410602124 | 180-2170 | 21110AA360 | 160-2070 |
| 2101058026 | 150-1080 | 987447 | 130-6061 | 944106921X | 180-2110 | 21111AA001 | 160-1120 |
| 2101058026 | 150-1080 | | | 951106921X | 180-2110 | 21111AA002 | 160-1120 |
| 2101058050 | 150-1080 | Opel | | 99610601153 | 180-2210 | 21111AA003 | 160-1120 |
| 2101058050 | 150-1080 | 1334037 | 155-1020 | | | 21111AA004 | 160-1120 |
| 2101061527 | 150-1530 | 1334038 | 155-1010 | Renault | | 21111AA005 | 160-1120 |
| 2101077A00 | 150-1390 | 1334060 | 155-2010 | 9806887 | 157-2060 | 21111AA006 | 160-1120 |
| 210107B000 | 150-2290 | 8942024771 | 140-1010 | 7701452781 | 157-2100 | 21111AA007 | 160-1120 |
| 210107Y025 | 150-2320 | | | 7701452782 | 157-2100 | 21111AA021 | 160-2040 |
| 210107Y026 | 150-2320 | Pantera | | 7701457595 | 157-2100 | 21111AA026 | 160-1150 |
| 210107Y026 | 150-2320 | D6AZ8501A | 125-1110 | 7701457771 | 157-2100 | 21111AA033 | 160-2050 |
| 2101085G25 | 150-1540 | | | 7701461173 | 157-2100 | 21111AA061 | 160-2060 |
| 2101085G25 | 150-1540 | Perkins | | 7701402962 | 157-1010 | 21111AA110 | 160-1120 |
| 2101085G25 | 150-1540 | 4131018 | 196-2049 | 7701450295 | 157-2090 | 21111AA230 | 160-2080 |
| 2101085G26 | 150-1540 | 4131018 | 196-2050 | 7701457447 | 157-2070 | 21111AA230 | 160-2080 |
| 2101085G26 | 150-1540 | 4131018 | 196-2051 | 7701457642 | 157-2020 | 21111AA240 | 160-2040 |
| 2101085G26 | 150-1540 | 41312479 | 196-2049 | 7701457671 | 157-1030 | 21111AA240 | 160-2040 |
| 2101085G27 | 150-1540 | 41312479 | 196-2050 | 7701462085 | 157-1050 | 21111AA380 | 160-2080 |
| 2101085G27 | 150-1540 | 41312479 | 196-2051 | 7701463182 | 157-2050 | 21111AA380 | 160-2080 |
| 2101086G00 | 150-1400 | 41312691 | 196-2049 | 7701502962 | 157-1010 | 310768100 | 160-1010 |
| 2101088R10 | 150-1420 | 41312691 | 196-2050 | B943385 | 157-2070 | | |
| 210108J000 | 150-2340 | 41312691 | 196-2051 | M943385 | 157-2070 | Sunbeam | |
| 2101097E00 | 150-2200 | 41312756 | 196-2052 | T1461239 | 157-2010 | 75221513 | 120-1010 |
| 21010AL525 | 150-2320 | 41312756 | 196-2053 | T1462085 | 157-1050 | | |
| 21010AL526 | 150-2320 | 41312918 | 196-2052 | T1462491 | 157-1100 | Suzuki | |
| 21010AL527 | 150-2320 | 41312918 | 196-2053 | T1463182 | 157-2050 | 1740060812 | 165-1160 |
| 21010B1762 | 150-2250 | 41313018 | 196-2022 | T1463397 | 157-1060 | 1740060815 | 165-1160 |
| 21010C0600 | 150-1080 | 41313048 | 196-2057 | | | 1740061820 | 165-2000 |
| 21010C0600 | 150-1080 | 41313201 | 196-2023 | Reo Truck | | 1740061820 | 165-2050 |
| 21010C0625 | 150-1080 | 41313201 | 196-2052 | 78903R91 | 138-3776 | 1740073811 | 165-1110 |
| 21010C0625 | 150-1080 | 41313201 | 196-2053 | | | 1740073821 | 165-1110 |
| 21010C0626 | 150-1080 | 4131E011 | 196-2068 | Saab | | 1740077810 | 165-2001 |
| 21010C0626 | 150-1080 | 2365731 | 196-2056 | 4395612 | 158-2030 | 1740078821 | 165-1110 |
| 21010C0627 | 150-1080 | | | 5958061 | 158-2020 | 1740082823 | 165-1150 |
| 21010C0627 | 150-1080 | Peugeot | | 8814501 | 158-1010 | 1740082850 | 165-1150 |
| 21010C4925 | 150-1080 | 1201.31 | 156-2130 | 8817900 | 158-1020 | 1740082851 | 165-1150 |
| 21010C4925 | 150-1080 | 1201.33 | 156-2010 | 8817918 | 158-1030 | 1740083810 | 165-1120 |
| 21010C6026 | 150-1210 | 1201.35 | 156-2140 | 8821944 | 158-2020 | 1740083811 | 165-1120 |
| 21010D0126 | 150-1200 | 1201.39 | 156-2110 | 8822710 | 158-2010 | 1740083811 | 165-1120 |
| 21010G3926 | 150-1173 | 1201.41 | 156-2080 | 8822744 | 158-2010 | 1740085830 | 165-1200 |
| 21010H5025 | 150-1110 | 1201.42 | 156-2070 | 8822793 | 158-2010 | | |
| 21010H7225 | 150-1110 | 1201.49 | 156-2160 | 9307893 | 158-1020 | TCM | |
| 21010H7227 | 150-1110 | 1201.55 | 156-2120 | 9321688 | 158-2000 | 2101013226 | 150-1010 |
| 21010J5125 | 150-1060 | 1201.71 | 156-2090 | 9321951 | 158-2010 | 2101048305 | 150-2500 |
| 21010L1125 | 150-1300 | 1202.37 | 156-1030 | 24467301 | 130-7350 | 2101078226 | 150-1060 |
| 21010L1625 | 150-2502 | 1202.55 | 156-2100 | 4770970 | 158-2020 | 21010L1125 | 150-1300 |
| 21010M6626 | 150-1020 | 1202.60 | 156-1010 | | | 21010L1625 | 150-2502 |
| 21010N5829 | 150-1173 | 1202.63 | 156-2150 | Scion | | 21010LI1625 | 150-2502 |
| 21010N5885 | 150-1173 | 1202.67 | 156-2100 | 1610029155 | 170-2101 | 9136103192 | 140-1130 |
| 21010N8527 | 150-1123 | 1202.69 | 156-1040 | | | Toyota | |
| 21010P7586 | 150-1160 | 1202.71 | 156-1050 | Simca | | 1311038021 | 170-1320 |
| 21010U6727 | 150-1123 | 1202.73 | 156-2060 | 19109800 | 120-1190 | 1321038060 | 170-1322 |
| 21010V5528 | 150-1310 | 1202.77 | 156-2020 | | | 1610009070 | 170-1920 |

Water Pump Interchange List - OE Numbers

| Their No. | Our No. | Their No. | Our No. | Their No. | Our No. | Their No. | Our No. |
|-----------------------|----------|--------------|----------|------------|----------|-------------------|----------|
| Toyota (Cont.) | | 1610049655 | 170-1520 | 1610088252 | 170-1270 | 1621038050 | 170-1322 |
| 1610009080 | 170-1980 | 1610049775 | 170-1820 | 1610088252 | 170-1270 | 1621038060 | 170-1322 |
| 1610009170 | 130-7360 | 1610059125 | 170-1420 | 1610088260 | 170-1450 | 1621041060 | 170-1402 |
| 1610009170 | 170-7360 | 1610059137 | 170-1610 | 1610088260 | 170-1450 | 1621041150 | 170-1282 |
| 161000H010 | 170-2470 | 1610059155 | 170-1790 | 1610176030 | 170-1870 | 1621042030 | 170-2222 |
| 1610016325 | 170-1990 | 1610059155 | 170-1790 | 1610340011 | 170-1360 | 1621042040 | 170-2822 |
| 1610019015 | 170-1300 | 1610059165 | 170-2100 | 1610340031 | 170-1060 | 1621042060 | 170-2232 |
| 1610019025 | 170-1380 | 1610059165 | 170-2100 | 1611019065 | 170-1680 | 1621061120 | 170-1612 |
| 1610019026 | 170-1430 | 1610059166 | 170-2100 | 1611019076 | 170-1580 | | |
| 1610019036 | 170-1490 | 1610059166 | 170-2100 | 1611019086 | 170-1580 | Triumph | |
| 1610019055 | 170-1500 | 1610059185 | 170-2120 | 1611019106 | 170-1930 | GWP128 | 113-1060 |
| 1610019065 | 170-1620 | 1610059185 | 170-2120 | 1611019107 | 170-2420 | GWP201 | 113-2110 |
| 1610019066 | 170-1510 | 1610059185 | 170-2221 | 1611019145 | 170-1830 | UKC774 | 113-2080 |
| 1610019085 | 170-1430 | 1610059185 | 170-2221 | 1611019146 | 170-1830 | | |
| 1610019105 | 170-1580 | 1610059186 | 170-2120 | 1611019175 | 170-1860 | Volkswagen | |
| 1610019115 | 170-1630 | 1610059186 | 170-2120 | 1611019176 | 170-1860 | 22121011 | 180-9020 |
| 1610019176 | 170-1860 | 1610059186 | 170-2221 | 1611019185 | 170-1860 | 22121011 | 180-9020 |
| 1610019195 | 170-1680 | 1610059186 | 170-2221 | 1611019205 | 170-1830 | 021121004 | 180-2105 |
| 1610019205 | 170-1780 | 1610059245 | 170-2100 | 1611019226 | 170-1930 | 021121004A | 180-2105 |
| 1610019225 | 170-1830 | 1610059245 | 170-2100 | 1611026021 | 170-1310 | 021121004AX | 180-2105 |
| 1610019226 | 170-1930 | 1610059255 | 170-1790 | 1611028010 | 170-1310 | 021121004X | 180-2105 |
| 1610019235 | 170-1910 | 1610059255 | 170-1790 | 1611038020 | 170-1340 | 022121011X | 180-9020 |
| 1610019235 | 170-1910 | 1610059257 | 170-1790 | 1611038021 | 170-1320 | 022121011X | 180-9020 |
| 1610019255 | 170-1830 | 1610059257 | 170-1790 | 1611038022 | 170-1320 | 023121005E | 180-1070 |
| 1610019265 | 170-1860 | 1610059275 | 170-1840 | 1611038031 | 170-1410 | 025121010A | 180-8379 |
| 1610019275 | 170-2321 | 1610060010 | 170-1070 | 1611039116 | 170-1120 | 025121010C | 180-2060 |
| 1610019275 | 170-2321 | 1610060013 | 170-1070 | 1611039116 | 170-1120 | 026121002E | 180-1070 |
| 1610019276 | 170-2321 | 1610060080 | 170-1080 | 1611049116 | 170-2270 | 026121005E | 180-1070 |
| 1610019276 | 170-2321 | 1610061010 | 170-1190 | 1611049126 | 170-2360 | 026121005H | 180-1070 |
| 1610019365 | 170-1860 | 1610061012 | 170-1190 | 1611069045 | 170-2161 | 026121005K | 180-2230 |
| 1610025012 | 170-1010 | 1610061041 | 170-1220 | 1611069045 | 170-2161 | 026121005L | 180-2230 |
| 1610026020 | 170-1350 | 1610061070 | 170-1880 | 1611079025 | 170-1770 | 028121004 | 180-2190 |
| 1610028040 | 170-2470 | 1610061080 | 170-1890 | 1611079026 | 170-1770 | 035121005E | 180-1100 |
| 1610029015 | 170-1020 | 1610061130 | 170-1890 | 1611079095 | 170-1670 | 037121005B | 180-1070 |
| 1610029026 | 170-1030 | 1610069035 | 170-1650 | 1611079115 | 170-1670 | 037121010A | 180-1070 |
| 1610029027 | 170-1090 | 1610069075 | 170-1530 | 1611079115 | 170-2107 | 038121011A | 180-2200 |
| 1610029045 | 170-1100 | 1610069076 | 170-1530 | 1611079185 | 170-1770 | 038121011AX | 180-2200 |
| 1610029085 | 170-1920 | 1610069085 | 170-1570 | 1611088250 | 170-1270 | 038121011G | 180-2200 |
| 1610029095 | 170-1980 | 1610069105 | 170-1740 | 1611088250 | 170-1270 | 038121011G | 180-2220 |
| 1610029115 | 170-2000 | 1610069105 | 170-1740 | 1611088251 | 170-1270 | 038121011G | 180-2220 |
| 1610029115 | 170-2000 | 1610069106 | 170-1740 | 1611088251 | 170-1270 | 052121005A | 180-2140 |
| 1610029145 | 170-2400 | 1610069106 | 170-1740 | 1611088252 | 170-1270 | 068121005B | 180-1010 |
| 1610029155 | 170-2101 | 1610069155 | 170-1730 | 1611088252 | 170-1270 | 068121005C | 180-1010 |
| 1610029175 | 130-7360 | 1610069206 | 170-1710 | 1611088260 | 170-1450 | 06A121011G | 180-2220 |
| 1610039035 | 170-1250 | 1610069215 | 170-1800 | 1611088260 | 170-1450 | 06A121011H | 180-2220 |
| 1610039065 | 170-1050 | 1610069225 | 170-1810 | 1612023010 | 170-2500 | 06A121011L | 180-2220 |
| 1610039065 | 170-1263 | 1610069235 | 170-1740 | 1612033010 | 170-1040 | 06A121011LV | 180-2220 |
| 1610039105 | 170-1740 | 1610069235 | 170-1740 | 1612034020 | 170-1040 | 06A121011LX | 180-2220 |
| 1610039105 | 170-1740 | 1610069305 | 170-1710 | 1612034100 | 170-1270 | 06A121011T | 180-2220 |
| 1610039116 | 170-1120 | 1610069325 | 170-1990 | 1612034100 | 170-1270 | 074121004 | 180-2115 |
| 1610039116 | 170-1120 | 1610069335 | 170-1710 | 1612034101 | 170-1270 | 078121004J | 180-2120 |
| 1610039135 | 170-1263 | 1610069345 | 170-1900 | 1612034101 | 170-1270 | 078121004JV | 180-2120 |
| 1610039315 | 170-1410 | 1610069385 | 170-2350 | 1612034140 | 170-1270 | 078121004Q | 180-2120 |
| 1610039316 | 170-1410 | 1610069395 | 170-1970 | 1612034140 | 170-1270 | 078121004QX | 180-2120 |
| 1610039345 | 170-1640 | 1610069396 | 170-1970 | 1612040060 | 170-1283 | 078121006 | 180-2120 |
| 1610039346 | 170-1640 | 1610069397 | 170-1970 | 1612040060 | 170-2083 | | |
| 1610040011 | 170-1360 | 161006939883 | 170-1970 | 1612041020 | 170-1150 | Volvo | |
| 1610049025 | 170-1280 | 1610069405 | 170-2103 | 1612045100 | 170-1550 | 272334 | 190-2120 |
| 1610049055 | 170-2501 | 1610069408 | 170-2103 | 1612045151 | 170-1760 | 272476 | 190-1080 |
| 1610049155 | 170-1140 | 1610076014 | 170-2502 | 1612047012 | 170-1210 | 418317 | 190-1010 |
| 1610049155 | 170-1140 | 1610079025 | 170-1770 | 1612047017 | 170-1210 | 418327 | 190-1010 |
| 1610049156 | 170-1140 | 1610079036 | 170-1540 | 1612049025 | 170-1280 | 418328 | 190-1010 |
| 1610049156 | 170-1140 | 1610079075 | 170-1770 | 1612078121 | 170-2504 | 1218096 | 190-2050 |
| 1610049165 | 170-1140 | 1610079126 | 170-1670 | 1612095052 | 170-2503 | 1218158 | 190-2040 |
| 1610049165 | 170-1140 | 1610079155 | 170-1850 | 1621026020 | 170-1312 | 3344253 | 190-2110 |
| 1610049166 | 170-1140 | 1610079155 | 170-1850 | 1621026020 | 170-1352 | 30650751 | 190-1080 |
| 1610049166 | 170-1140 | 1610079185 | 170-1770 | 1621028020 | 170-1312 | 30650751 | 190-1080 |
| 1610049185 | 170-1150 | 1610079225 | 170-1960 | 1621031010 | 170-1542 | 30650751 | 190-1080 |
| 1610049225 | 170-1150 | 1610079245 | 170-1960 | 1621038022 | 170-1322 | 12571857 | 180-1060 |
| 1610049415 | 170-1240 | 1610079255 | 170-1960 | 1621038030 | 170-1342 | 12698742 | 190-1050 |
| 1610049505 | 170-1280 | 1610079445 | 170-3310 | 1621038050 | 170-1312 | 13360292 | 190-2110 |

Water Pump Interchange List - OE Numbers

| Their No. | Our No. | Their No. | Our No. | Their No. | Our No. | Their No. | Our No. |
|----------------------|----------|-----------|---------|-----------|---------|-----------|---------|
| Volvo (Cont.) | | | | | | | |
| 25756195 | 190-1030 | | | | | | |
| 2706810 | 190-1030 | | | | | | |
| 2712750 | 190-1040 | | | | | | |
| 2716470 | 190-1070 | | | | | | |
| 2718302 | 190-1040 | | | | | | |
| 2718559 | 190-1070 | | | | | | |
| 2719847 | 190-1080 | | | | | | |
| 2719847 | 190-2090 | | | | | | |
| 2719854 | 190-1080 | | | | | | |
| 2724763 | 190-1080 | | | | | | |
| 2724763 | 190-2120 | | | | | | |
| 2742161 | 190-1080 | | | | | | |
| 2742161 | 190-1080 | | | | | | |
| 2742161 | 190-2120 | | | | | | |
| 2756195 | 190-1030 | | | | | | |
| 32830432 | 190-2110 | | | | | | |
| 33442526 | 190-2110 | | | | | | |
| 4610945 | 190-2060 | | | | | | |
| 8353906 | 130-6060 | | | | | | |
| 8563645 | 130-6060 | | | | | | |
| White Truck | | | | | | | |
| AR04283 | 196-2002 | | | | | | |
| BM50446 | 196-2018 | | | | | | |
| BM76506 | 196-2018 | | | | | | |
| Yale | | | | | | | |
| 505960579 | 145-2500 | | | | | | |
| 518591007 | 145-2501 | | | | | | |
| 900535801 | 145-2503 | | | | | | |
| 9012302802 | 145-1290 | | | | | | |
| 901579801 | 145-1320 | | | | | | |
| 902230300 | 145-2502 | | | | | | |
| Yugo | | | | | | | |
| 46641248 | 195-1100 | | | | | | |